Dart Aerospace Ltd. 10 SOOT 1127 Thursday, 22/11/2007 12:57:21 PM Lin ta Lacelle **Process Sheet Drawing Name** : REWORK : CC-DAR01 Dart Aerospace Ltd. Orstomer : 35962 ---Job Number Estimate Number : 10804 : D2807041 : NA Part Number 3.0. Number S.O. No. : MA - ECN 1019 **Drawing Number** : 22/11/2007 Tis Issue Project Number Prsht Rev. : SMALL /MED FAB **Drawing Revision** Type First Issue Material : 35961 Previous Run Um: Each **Due Date** Written By Checked & Approved By Comment Additional Product Lieb Number: Description: Machine Or Operation: Seq. #: PACKAGING RESOURCE #1 PACKAGING 1 1.0 Comment: PACKAGING RESOURCE #1 REMOVE FROM STOCK: D2807 B 3 3941 SMALL & MEDIUM FAB RESOURCE 1 2.0 Commert: SMALL & MEDIUM FAB RESOURCE 1 ADD D3671-1 PLACARD B 356/3 TO D2807 (BECOMES D2807-041) PER DRWG D2807-041 Gas Spring (Suppo 3.0 D2807 50.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qty.: Gas Spring (Support Prop) D36711 4.0 1.0000 Each(s)/Unit Total: 50.0000 Each(s) Comment: Qtv.: **PLACARD** INSPECT WORK TO CURRENT STEP QC5 5.0 Comment: INSPECT WORK TO CURRENT STEP

Page 1

Form: rprocess

Thursday, 22/11/2007 12:57:21 PM Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: REWORK

Job Number: 35962

Part Number: D2807041

Job Number:

Seq. #:

Machine Or Operation:

Description:

6.0

PACKAGING 1


PACKAGING RESOURCE #1


Comment: PACKAGING RESOURCE #1 RESTOCK USING NEW B/N

Job Completion



QC21 Final inspection W/O release I





D2807-1 GAS SPRING

NOTES:

- 1) MATERIAL: NONE SEE NOTE #8
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: N/A
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: 0.147 lbs
- 8) SPECIFICATION: SS GAS SPRING

ACCEPTABLE LOAD RANGE IS 25 Ib MIN TO 45 Ib MAX M5x0.8 THREADS

POSSIBLE SUPPLIER: ArvinMeritor Motion Control Systems, Leicester, UK P/N: SXF6S6050080S6L-115N (REF: 80mm LONG CYLINDER, 50mm STROKE,

115N LOAD)

D2807-041 GAS SPRING ASSEMBLY

NOTES:

- 1) MATERIAL: NONE
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: N/A
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: 0.179 lbs

D2807-041 GAS SPRING ASSEMBLY PARTS LIST

QTY -041	PART NUMBER	DESCRIPTION	
X	D2807-041	GAS SPRING ASSEMBLY	
- ₁	D2807-1	GAS SPRING	
2	D2807-3	LUG	
1	D3671-1	PLACARD	



REV.	DESCRIPTION	BY	DATE
A	NEW ISSUE	DS	00.11.03
В	ADD FINISH	CP	05.03.16
C	CHANGE SPRING TO SS, ADD -3 LUG	CP	05.05.25
D	ADDED D367"-1 PLACARD ADDED -041 ASSEMBLY UPDATED DWG	DC	07.09.27

DESIGN	gr	DART AEROSPACE LTD		
DRAWN	Lt	HAWKESBURY, ONTARIO, CANADA		
CHECKED	H)	DRAWING NO.	REV. D	
MFG. APPR.	M	D2807	SHEET 1 OF 2	
APPROVED	1001	TITLE	SCALE	
DE APPR.		GAS SPRING	1:1	
DATE 07.0	-,	COPYRIGHT © 2000 BY DART AEROSPACE LTD THE DOLUMET'S PRINTE AND CAN DEBTURY AND EXEMPLE AS THE COMMESSION EXEMPTION OF DEBTURY OF THE PRINTED AND THE RESULT AND THE RESUL		

3

٠,

,